SOLID EDGE
VELOCITY SERIES

Tutorial: ***Set***

Templates & Reports CAAP

Project: ***Rocket (Draft)***

cad / cam / pdm / cae | CAAP®

Solution Partner PLM | SIEMENS

In this tutorial the instructions to download and set the Templates and Reports of CAAP will be explained. The Templates and Reports can be used by making drawings. The drawings in these tutorials are made by using the Templates and Reports of CAAP.

How restore the default Templates and Reports will be explained at the end of this tutorial.

1	1. Start your internet browser. 2. Go to the website: **http://www.caap.nl/paginas/tutorials**	
2	3. Click on the **Templates & Reports instellingen** picture.	
3	4. Click the **Templates voor lesbrieven** link.	

4	5. Create a map on your computer, which is easy to find. Named: *Templates & Reports CAAP*. 6. Click on **Save**. 7. Exit the browser. ***Hint:*** *When you use another web browser as shown, the lay-out can be different.*	
5	8. Extract the **Templates_voor_lesbrieven.zip** file. This can be done clicking RMB on the file and click **extract here**. ***Hint:*** *It depends on the installed program on the computer with options are available.*	
6	1. Start **Solid Edge.**	

7	2. Click the **Application Button**. 3. Click the **Solid Edge Options**.	
8	4. Click the **File Locations** tab. 5. Click on **Reports**. 6. Click the **Modify** button. 	
9	7. Browse to the *Reports* in the *Templates & Reports CAAP* folder. Click the folder **Reports**. 8. Click the **OK** button.	

10	1. Now click on **User Templates**. 2. Click the **Modify** button. 	
11	3. Browse to the *Reports* in the *Templates & Reports CAAP* folder. Click the folder **Templates**. 4. Click the **OK** button.	
12	5. Click the **Apply** button. 6. Click the **OK** button.	

13	1. Click on **ISO Draft.** 	
14	The **Templates en Reports** for drawings are ready.	
15	Now there will be explained how to restore the default **Templates** and **Reports** of **Solid Edge**.	

16	1. Start **Solid Edge.**	
17	2. Click the **Application Button**. 3. Click on **Solid Edge Options**.	
18	4. Click the **File Locations** tab. 5. Click on **Reports**. 6. Click the **Reset** button. 	

19	1. Click on **User Templates**. 2. Click the **Reset** button. 	
20	3. Click the **Apply** button. 4. Click the **OK** button.	
21	1. Click on **<u>ISO Draft.</u>** 	

22	The default **Templates en Reports** of **Solid Edge** are set.	