




F1 – M3 Pan Head
Slotted Machine Screw




F2 – M3 Nyloc nut




F3– M5 Split Lock Washer




F5 – M5 x 20 mm
Socket Head Cap Screw




F6 – M6 Washer




F7 – M6 Nyloc Nut




F8 – M6 x 12 mm
Socket Head Cap Screw




F9 – M6 x 20 mm Cap Screw




F10 – M8 Washer




F11 – Nylon Washer




F12 – M8 Washer




F13 – M8 Nyloc Nut




F14 – M8 Nut




F15 – M8 x 20 mm Bolt




F16 – M8 x 30 mm Bolt




F17 – M8 x 50 mm Bolt




F20 – M10 Nyloc Nut




F23 – 5MM Roll Pin




F32 M8 x 16 mm Set Screw




F21 – M10 x 20 mm Bolt




F33 – M6 x 35 mm
Socket Head Cap Screw




F18 – M10 Washer




F24 – 3.2 x 10mm Pop Rivet



F22 – M10 x 40 mm
Socket Head Cap Screw



F19 – M10 Split Lock Washer



F25 – 16 mm Rubber Grommet

